

2020

Concordia College

Moorhead MN

Campus Public Safety

Fire Safety Report

CONCORDIA COLLEGE

FIRE SAFETY

Students residing in Concordia College residence halls are provided with training and information that will enable them to prevent, report, or respond to a fire emergency within residence halls.

STUDENT TRAINING

Students receive the majority of their training from their residence hall staff at the start of each academic year.

Students are provided with information regarding their floor, their building, as well as fire safety. Students are shown the location of fire pull stations, fire safety equipment (fire extinguishers and smoke detectors) and evacuation routes from the building.

Upon moving into a hall, every student should become familiar with fire exit routes and locations of fire extinguishers. When a fire alarm sounds, all persons must immediately evacuate the building, exiting by the most direct safe route. Occupants must evacuate to points sufficient to ensure their personal safety. All occupants must evacuate in a timely manner.

Detailed placards with fire evacuation procedures and emergency exits are posted on each floor of all residence halls. Placards with the fire emergency exit plan are posted in each room. Also, there is a smoke detector located in each residence hall room.

Students are trained in the following fire evacuation procedures:

Before the Fire:

- Know the location of all pull stations on your floor
- Know the location of all fire extinguishers on your floor
- Know the nearest exit and alternative exits, in the event that one is blocked

On Discovering a Fire:

- If you are able to extinguish the fire without putting yourself at risk, do so. If not, leave immediately
- Close your room/apartment door
- Sound the building alarm while exiting
- Call 9-911 from the front entry and report the fire then call Public Safety at 3123

CONCORDIA COLLEGE

Upon Hearing the Alarm:

- Dress for the weather
- Close windows
- Open drapes/shutters
- Turn on lights
- Check door to see if it is hot
- Check hallway for smoke
- Lock door as you exit

FIRE DRILLS

In order to test the fire alarm system and observe student and staff behavior, the college conducts fire evacuation drills. These drills are conducted twice each academic year in the residence halls. Fire alarm and facilities deficiencies are reported to Facilities Management and Risk Management. Student behavioral issues are reported to Residence Life.

RESIDENCE HALL RULES REGARDING FIRE SAFETY

The following are prohibited: tampering with fire or safety-related equipment (fire alarms, smoke detectors, fire extinguishers, exit alarms, door closers, etc.), use of multi-headed extension cords, use of space heaters or air conditioners, use of rubber-backed carpeting, use of halogen lights or lamps, tampering with fixed devices (electrical outlets, light switches, cable television outlets, or phone jacks), use of candles, the use of grills on balconies, smoking, and the use of incense are all prohibited activities.

The use of all tobacco products is prohibited on College property.

One small refrigerator and microwave oven are allowed in each room. The use of appliances which utilize heating elements (such as hot pots, hot plates, popcorn poppers, toasters, etc...) is strongly discouraged.

Hallways and stairways must be accessible at all times, do not leave anything in hallways or stairways.

CONCORDIA COLLEGE

FUTURE IMPROVEMENTS

Concordia College continues to evaluate the fire systems in each residence hall to determine if improvements are necessary. The International Apartments and Brown Hall are not occupied. No upgrades or improvements scheduled at this time.

REPORTING OFFICIALS

Once the proper emergency personnel have been notified, the Hall Director is responsible for notifying the Director of Residence Life who, in turn, will notify other key individuals such as the Vice President, the Director of Public Safety, Risk Management, and Facilities Management as necessary.

ANNUAL CLERY REPORT

A copy of Concordia's current Clery Report may be obtained by contacting Concordia Public Safety at (218) 299-3123 or online at:

<http://www.concordiacollege.edu/cleryreport>

CONCORDIA COLLEGE

| Concordia College 2020 Fire Matrix | | | | | | | |
|---|--|-------------------------------------|----------------------------------|------------------------|----------------------------------|----------------------------------|--|
| Concordia College Residential Facilities | Fire Alarm Monitoring Done Off Site by Contract Company | Partial (1) Sprinkler System | Full (2) Sprinkler System | Smoke Detection | Fire Extinguisher Devices | Evacuation Plans/Placards | Number of evacuation (fire) drills each academic year |
| Boe-Olson Apts | X | | | X | X | X | 2 |
| Bogstad East | X | | | X | X | X | 2 |
| Bogstad Manor | X | | | X | X | X | 2 |
| Brown Hall (unoccupied) | X | X | | X | X | X | 2 |
| Eco House | | | | X | X | | 0 |
| Erickson Hall | X | | X | X | X | X | 2 |
| Fjelstad Hall | X | | | X | X | X | 0 |
| Hallett Hall | X | | X | X | X | X | 2 |
| Hoyum Hall | X | | | X | X | X | 2 |
| International Center (unoccupied) | | | | X | X | X | 0 |
| Livedalen Hall | X | | | X | X | X | 2 |
| Park Region | X | | | X | X | X | 2 |
| Townhouse East | X | | X | X | X | X | 2 |
| Townhouse West | X | | X | X | X | X | 2 |

(1) Partial Sprinkler System is defined as having sprinklers in the commons area only.

(2) Full Sprinkler System is defined as having sprinklers in both the commons area and individual rooms.

CONCORDIA COLLEGE

Concordia College 2019 Fire Statistics

| Concordia College Residential Facilities | Total Fires in Each Building | Fire Number | Date | Time | Cause of Fire | Number of Injuries that Required Treatment at a Medical Facility | Number of Deaths Related to a Fire | Value of Property Damage Caused by Fire | Case Number |
|--|------------------------------|-------------|-------|-------|----------------------|--|------------------------------------|---|-------------|
| Boe-Olson Apts | 0 | | | | | | | | |
| Bogstad East | 0 | | | | | | | | |
| Bogstad Manor | 0 | | | | | | | | |
| Brown Hall | 0 | | | | | | | | |
| Eco House | 0 | | | | | | | | |
| Fjelstad Hall | 1 | 1 | 10/29 | 10:10 | Cooking in microwave | 0 | 0 | 0 | 2019-102901 |
| Hallett Hall | 0 | | | | | | | | |
| Hoyum Hall | 0 | | | | | | | | |
| International Center | 0 | | | | | | | | |
| Livedalen Hall | 0 | | | | | | | | |
| Park Region | 0 | | | | | | | | |
| Townhouse East | 0 | | | | | | | | |
| Townhouse West | 0 | | | | | | | | |

2019 Fire Call Log

| Date | Time | General Location | Nature |
|------|------|------------------|--------|
| | | | |

CONCORDIA COLLEGE

| Concordia College 2018 Fire Statistics | | | | | | | | | |
|---|-------------------------------------|--------------------|-------------|-------------|----------------------|---|---|--|--------------------|
| Concordia College Residential Facilities | Total Fires in Each Building | Fire Number | Date | Time | Cause of Fire | Number of Injuries that Required Treatment at a Medical Facility | Number of Deaths Related to a Fire | Value of Property Damage Caused by Fire | Case Number |
| Boe-Olson Apts | 0 | | | | | | | | |
| Bogstad East | 0 | | | | | | | | |
| Bogstad Manor | 0 | | | | | | | | |
| Brown Hall | 0 | | | | | | | | |
| Eco House | 0 | | | | | | | | |
| Fjelstad Hall | 0 | | | | | | | | |
| Hallett Hall | 0 | | | | | | | | |
| Hoyum Hall | 0 | | | | | | | | |
| International Center | 0 | | | | | | | | |
| Livedalen Hall | 0 | | | | | | | | |
| Park Region | 0 | | | | | | | | |
| Townhouse East | 0 | | | | | | | | |
| Townhouse West | 0 | | | | | | | | |

| 2018 Fire Call Log | | | |
|---------------------------|-------------|-------------------------|---------------|
| Date | Time | General Location | Nature |
| | | | |

CONCORDIA COLLEGE

| Concordia College 2017 Fire Statistics | | | | | | | | | |
|---|-------------------------------------|--------------------|-------------|-------------|----------------------|---|---|--|--------------------|
| Concordia College Residential Facilities | Total Fires in Each Building | Fire Number | Date | Time | Cause of Fire | Number of Injuries that Required Treatment at a Medical Facility | Number of Deaths Related to a Fire | Value of Property Damage Caused by Fire | Case Number |
| Boe-Olson Apts | 0 | | | | | | | | |
| Bogstad East | 0 | | | | | | | | |
| Bogstad Manor | 0 | | | | | | | | |
| Brown Hall | 0 | | | | | | | | |
| Eco House | 0 | | | | | | | | |
| Fjelstad Hall (temporary academic use) | 0 | | | | | | | | |
| Hallett Hall | 0 | | | | | | | | |
| Hoyum Hall | 0 | | | | | | | | |
| International Center (unoccupied) | 0 | | | | | | | | |
| Livedalen Hall | 0 | | | | | | | | |
| Park Region | 0 | | | | | | | | |
| Townhouse East | 0 | | | | | | | | |
| Townhouse West | 0 | | | | | | | | |

| 2017 Fire Call Log | | | |
|---------------------------|-------------|-------------------------|---------------|
| Date | Time | General Location | Nature |
| | | | |